

Tabella perdite di carico

Tubi Acciaio saldati da ½" a 4"

Q = Portata litri/sec

V = Velocità m/sec

J = Perdita di carico = m/km

q _l	DN	1/2"	3/4"	1"	1" 1/4	1" 1/2	2"	2" 1/2	3"	4"
	ø int.	16,7	21,7	28,5	36,6	42,5	53,9	69,7	81,7	107,1
0,1	V	0,46	0,27	0,16						
	J	26,32	7,35	1,95						
0,2	V	0,91	0,54	0,31	0,19					
	J	94,87	26,50	7,03	2,08					
0,5	V	2,28	1,35	0,78	0,48	0,35	0,22			
	J	516,79	144,34	38,27	11,32	5,47	1,72			
1,0	V		2,71	1,57	0,95	0,71	0,44	0,26	0,19	
	J		520,34	137,96	40,80	19,71	6,19	1,77	0,82	
1,5	V			2,35	1,43	1,06	0,66	0,39	0,29	0,17
	J			292,10	86,39	41,72	13,12	3,75	1,73	0,46
2,0	V			3,14	1,90	1,41	0,88	0,52	0,38	0,22
	J			497,35	147,10	71,04	22,33	6,39	2,95	0,79
2,5	V				2,38	1,76	1,10	0,66	0,48	0,28
	J				222,27	107,35	33,74	9,65	4,45	1,19
3,0	V				2,85	2,12	1,32	0,79	0,57	0,33
	J				311,44	150,41	47,28	13,52	6,24	1,67
3,5	V				3,33	2,47	1,54	0,92	0,67	0,39
	J				414,21	200,04	62,88	17,98	8,30	2,22
4,0	V				3,81	2,82	1,75	1,05	0,76	0,44
	J				530,28	256,10	80,51	23,02	10,62	2,84
4,5	V					3,18	1,97	1,18	0,86	0,50
	J					318,45	100,10	28,63	13,21	3,53
5,0	V					3,53	2,19	1,31	0,95	0,56
	J					386,98	121,65	34,79	16,05	4,29
5,5	V					3,88	2,41	1,44	1,05	0,61
	J					461,60	145,11	41,49	19,14	5,12
6,0	V					4,23	2,63	1,57	1,15	0,67
	J					542,22	170,45	48,74	22,49	6,02
7,0	V						3,07	1,84	1,34	0,78
	J						226,70	64,82	29,91	8,00
8,0	V						3,51	2,10	1,53	0,89
	J						290,22	82,99	38,29	10,24

Tabella perdite di carico

Tubi Acciaio saldati da ½" a 4"

Q = Portata litri/sec

V = Velocità m/sec

J = Perdita di carico = m/km

9,0	V						3,95	2,36	1,72	1,00
	J						360,88	103,19	47,61	12,74
10,0	V						4,39	2,62	1,91	1,11
	J						438,54	125,40	57,85	15,48
11,0	V						4,83	2,89	2,10	1,22
	J						523,11	149,58	69,01	18,47
12,0	V							3,15	2,29	1,33
	J							175,71	81,06	21,69
13,0	V							3,41	2,48	1,44
	J							203,75	94,00	25,15
14,0	V							3,67	2,67	1,56
	J							233,69	107,81	28,85
15,0	V							3,94	2,86	1,67
	J							265,51	122,49	32,78
16,0	V							4,20	3,06	1,78
	J							299,18	138,02	36,93
17,0	V							4,46	3,25	1,89
	J							334,69	154,40	41,31
18,0	V							4,72	3,44	2,00
	J							372,01	171,63	45,92
19,0	V							4,98	3,63	2,11
	J							411,15	189,68	50,75
20,0	V							5,25	3,82	2,22
	J							452,08	208,56	55,81
25,0	V								4,77	2,78
	J								315,15	84,33
30,0	V								5,73	3,33
	J								441,57	118,15